





A		10x40	x20
B		6,3x60	x2
C		M6x60	x4
D		M6x10x13	x4
E		D35	x2
F		7x60	x2

G		7x50	x4
H		5x38	x14
J		3,5x35	x25
K		3,5x20	x22
L		102x30x6	x1
M		4mm	x1


①



A		10x40	x20
---	--	-------	-----





5





J		3,5x35	x2
---	---	--------	----

6




G		7x50	x4
---	---	------	----

7







NB!



H		5x38	x4
J		3,5x35	x4

8




H		5x38	x10
J		3,5x35	x10

L



102x60x30 x1

9



L		102x30x6	x1
---	--	----------	----

J		3,5x35	x9
K		3,5x20	x22